



228 Ambassador Drive
Mississauga ON
Canada
L5T 2J2

May 14, 2014

Edna Prado
Office of Engineering and Technology

Re: FCC ID BZ5DTR10SC
Correspondence Reference number 45761

With regards to the missing schematic diagrams for this product, please find attached our publication: "TSM20-399 Frontier 10W VHF.pdf" service manual which includes the schematics and circuit description as well as a separate file/document with only the schematics. This information was inadvertently omitted from the original application. I apologize for any inconvenience this may have caused.

If there is anything else you need please do not hesitate to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "John Tremblay", is written in a cursive style.

John Tremblay
V. P. Engineering



LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcana.com Email: sales@larcana.com