

RE: 5808W3AP

Tim,

You wrote, I reply:

Regards Greg

1) Users Manual missing 15.21 information. Please update.

Please see the new uploaded exhibit: EXHIBIT 7A

2) Please explain how tamper and maintenance signals meet the 5 second requirement as well.

The supervision signal ("maintenance signal") is generated by the RF Control micro: IC3 (see block diagram or schematic)  
If a tamper event occurs it is also processed by the micro. The micro will not allow violation of the 5 second rule by the supervision signal or the tamper.

3) Some data sheets mention the incorrect year of C63.4. Please correct.

Please see the new uploaded exhibit: 5808W3AP EXHIBIT 5-3A

4) 1575 MHz appears to fall in a restricted band and therefore the incorrect limit is applied. Please correct.

Please see the new uploaded exhibit: 5808W3AP EXHIBIT 5-3A