Motorola Inc, FCC ID: IHDT6HA1, Assessment NO.: AN07T6802, Notice#1 Inbox

hide details May 14 (22 hours ago) A Reply from **Tim Dwyer** <Timothy_Dwyer@ieee.org> to eric.wong@tw.ccsemc.com, aven.zhou@cn.ccsemc.com cc "Timothy M. Dwyer" <tim.dwyer@ccsemc.com> date May 14, 2007 10:31 AM subject Motorola Inc, FCC ID: IHDT6HA1, Assessment NO.: AN07T6802, Notice#1 mailed-by gmail.com

Dear Eric, Aven,

The review of the FCC application is complete. The only items found are related to information that must be included in the user manual. If you have questions, please email.

AN07T6802 Motorola IHDT6HA1

Q1: Since the device is too small to include the statement required by 15.19, it must be included in the user manual. Please revise the user manual to include the statement:

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Q2: The user manual should also include the following statements from 15.105 and 15.21.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- -Reorient or relocate the receiving antenna.
- -Increase the separation between the equipment and receiver.
- -Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- -Consult the dealer or an experienced radio/TV technician for help.

Changes or modifications not expressly approved by Motorola could void the user's authority to operate this equipment.

Best regards,

Tim Dwyer CCS TCB Technical Reviewer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.



Dear TimDwyer,

The attached is the update Usermanual. Thank you for your sincere help.

subject Re:Motorola Inc, FCC ID: IHDT6HA1, Assessment NO.: AN07T6802, Notice#1

Best regards!

aven.zhou

Compliance Certification Service(Shenzhen) Inc.

Tel: 0755-28055000 ext. 601

E-mail: aven.zhou@cn.ccsemc.com
MSN : tilly_ping@hotmail.com

"Tim Dwyer" <Timothy_Dwyer@ieee.

org> 收件人: <u>eric.wong@tw.ccsemc.com</u>, <u>aven.zhou@cn.</u>

副本抄送: "Timothy M. Dwyer" < <u>tim.dwyer@ccsemc.com</u>>

主旨: Motorola Inc, FCC ID: IHDT6HA1, Assessment NO.:

007-05-14 22.31 AN07T6802, Notice#1

Show quoted text -

UserMan_0515.pdf



117K View as HTML

Download