


Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos





Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos




Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos





Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos





Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos





Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos




Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-06

Report No.: 60.870.13.026.01F

Model No.: AAPCAM23

Photo of EUT – Internal EUT Photos

