



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 5, 2005

RE: ASUSTek Computer Inc.

FCC ID: MSQV66

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Before the grants can be issued, we have discovered that the applicant has an outstanding issue with the FCC. We noted the following error code in the FCC system:

The applicant FCC Registration Number(FRN), 0005819321, is associated with outstanding receivables. Issuance of new or the reprint of grants will not be permitted.

Please contact Bette Taube directly with the FCC to resolve this issue. (bette.taube@fcc.gov)

- 2) New 731 form for previous item 1 does not appear to have been received. Please provide. This should have addressed the following issues.
 - a) Section I - 3(a) and 3(b) must list the FCC ID to be Certified. Please correct.
 - b) Section II - Please fill in correct address for ATL or the appropriate company in section 2(a).
 - c) Section III - Section 6 of the 731 form must be filled in for (a)(b)(c)(d). For Part 22, (a) would be listed for ERP. For Part 24, (b) would be listed as EIRP. Additionally, please fill in Section 4(a)/(b), 7, 8, or 9.
 - d) Section IV must be filled in as appropriate.
- 3) New users manual for previous item 12 & 13 does not appear to have been received. This should have addressed the following issues:
 - a) FCC ID specified within the users manual does not match this application. Please correct.
 - b) Page 66 of the users manual mentions a 20 cm spacing which is not applicable to this device and should be removed. Please correct.

Part 24 Review

- 4) FYI.....The bandwidth test is still not reported as per our discussions. However estimations determine it to be close to what is expected.

SAR Review

- 5) New users manual for previous item 31 does not appear to have been received. This should have addressed the following issues:
 - a) When information reported in the users manual reports SAR values, it should match the SAR values measured. Please correct the users manual to report the correct SAR values.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination.

Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.