



Cisco-Linksys LLC

121 Theory Drive Irvine, CA 92617 (USA)

Phone: 949-261-1288 Fax: 949-823-3002

Date: July 3, 2008

To whom it may concern

It is acknowledged by Cisco-Linksys LLC.. that the modification list below will be installed to our Model: WRVS4400N V2 in order to comply with FCC/CE Approval requirements. These modifications will be incorporated into each unit sold and mass production under the rules.

1. To cut off DDR_1.25V trace and added one bead (PBY201209T-102Y-N) in series and added one bypass capacitor 2.2nf on PCB bottom layers.
2. Added copper tape with ground by eight points on pcb top layers.
3. To Cut off 1.2V power trace and link 1.2V both sides ground on pcb bottom layers.
4. Add one ferrite core(K5B T9*8*5) of the ant cable.

Yours sincerely,

Darrell Tennis/ Manager, Regulatory Compliance
Cisco-Linksys LLC
TEL: +1 949-910-7048
FAX: +1-949-823-3002
E-Mail: dtennis@cisco.com