## 9.2.2. 5G NR n77 (FCC Part 27 3450-3550MHz, MIMO)




5G NR n77 10MHz BPSK Low Channel RB1-0 Port A




5G NR n77 10MHz BPSK Low Channel RB1-23 Port A




5G NR n77 10MHz BPSK Low Channel RB1-0 Port B




5G NR n77 10MHz BPSK Low Channel RB1-23 Port B




5G NR n77 10MHz BPSK Low Channel RB1-0 Port A+B




5G NR n77 10MHz BPSK Low Channel RB1-23 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 10MHz BPSK Mid Channel RB1-0 Port A




5G NR n77 10MHz BPSK Mid Channel RB1-23 Port A




5G NR n77 10MHz BPSK Mid Channel RB1-0 Port B




5G NR n77 10MHz BPSK Mid Channel RB1-23 Port B




5G NR n77 10MHz BPSK Mid Channel RB1-0 Port A+B




5G NR n77 10MHz BPSK Mid Channel RB1-23 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 10MHz BPSK High Channel RB1-0 Port A




5G NR n77 10MHz BPSK High Channel RB1-23 Port A




5G NR n77 10MHz BPSK High Channel RB1-0 Port B




5G NR n77 10MHz BPSK High Channel RB1-23 Port B




5G NR n77 10MHz BPSK High Channel RB1-0 Port A+B




5G NR n77 10MHz BPSK High Channel RB1-23 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 10MHz BPSK Low Channel RB24-0 Port A




5G NR n77 10MHz BPSK Mid Channel RB24-0 Port A




5G NR n77 10MHz BPSK Low Channel RB24-0 Port B




5G NR n77 10MHz BPSK Mid Channel RB24-0 Port B




5G NR n77 10MHz BPSK Low Channel RB24-0 Port A+B




5G NR n77 10MHz BPSK Mid Channel RB24-0 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 10MHz BPSK High Channel RB24-0 Port A




5G NR n77 10MHz BPSK High Channel RB24-0 Port B




5G NR n77 10MHz BPSK High Channel RB24-0 Port A+B

Intentionally Blank



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 15MHz BPSK Low Channel RB1-0 Port A




5G NR n77 15MHz BPSK Low Channel RB1-37 Port A




5G NR n77 15MHz BPSK Low Channel RB1-0 Port B




5G NR n77 15MHz BPSK Low Channel RB1-37 Port B




5G NR n77 15MHz BPSK Low Channel RB1-0 Port A+B




5G NR n77 15MHz BPSK Low Channel RB1-37 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 15MHz BPSK Mid Channel RB1-0 Port A




5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A




5G NR n77 15MHz BPSK Mid Channel RB1-0 Port B




5G NR n77 15MHz BPSK Mid Channel RB1-37 Port B




5G NR n77 15MHz BPSK Mid Channel RB1-0 Port A+B




5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 15MHz BPSK High Channel RB1-0 Port A




5G NR n77 15MHz BPSK High Channel RB1-37 Port A




5G NR n77 15MHz BPSK High Channel RB1-0 Port B




5G NR n77 15MHz BPSK High Channel RB1-37 Port B




5G NR n77 15MHz BPSK High Channel RB1-0 Port A+B




5G NR n77 15MHz BPSK High Channel RB1-37 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




5G NR n77 15MHz BPSK Low Channel RB36-0 Port A




5G NR n77 15MHz BPSK Mid Channel RB36-0 Port A




5G NR n77 15MHz BPSK Low Channel RB36-0 Port B




5G NR n77 15MHz BPSK Mid Channel RB36-0 Port B




5G NR n77 15MHz BPSK Low Channel RB36-0 Port A+B




5G NR n77 15MHz BPSK Mid Channel RB36-0 Port A+B



UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*