1.The change under this application is one IC added on the board relative to the previous version, IC function is automatic software repair. as shown in Fig

Before Class II permissive change

After Class II permissive change

2.A flash ic 8G change to 16 G on the PCB board.PCB photos no change.