

5G NR n48 10MHz QPSK High Channel RB1-0 Port A, ID:27957



5G NR n48 10MHz QPSK High Channel RB1-23 Port A, ID:27957



5G NR n48 10MHz QPSK High Channel RB1-0 Port B, ID:27957



5G NR n48 10MHz QPSK High Channel RB1-23 Port B, ID:27957



5G NR n48 10MHz QPSK High Channel RB1-0 Port A+B, ID:27957



5G NR n48 10MHz QPSK High Channel RB1-23 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 10MHz QPSK Low Channel RB24-0 Port A, ID:27957



5G NR n48 10MHz QPSK Mid Channel RB24-0 Port A, ID:27957



5G NR n48 10MHz QPSK Low Channel RB24-0 Port B, ID:27957



5G NR n48 10MHz QPSK Mid Channel RB24-0 Port B, ID:27957



5G NR n48 10MHz QPSK Low Channel RB24-0 Port A+B, ID:27957



5G NR n48 10MHz QPSK Mid Channel RB24-0 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 10MHz QPSK High Channel RB24-0 Port A, ID:27957



5G NR n48 10MHz QPSK High Channel RB24-0 Port B, ID:27957



5G NR n48 10MHz QPSK High Channel RB24-0 Port A+B, ID:27957

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz QPSK Low Channel RB1-0 Port A, ID:27957



5G NR n48 15MHz QPSK Low Channel RB1-37 Port A, ID:27957



5G NR n48 15MHz QPSK Low Channel RB1-0 Port B, ID:27957



5G NR n48 15MHz QPSK Low Channel RB1-37 Port B, ID:27957



5G NR n48 15MHz QPSK Low Channel RB1-0 Port A+B, ID:27957



5G NR n48 15MHz QPSK Low Channel RB1-37 Port A+B, ID:27957

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz QPSK Middle Channel RB1-0 Port A, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB1-37 Port A, ID:27957



5G NR n48 15MHz QPSK Middle Channel RB1-0 Port B, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB1-37 Port B, ID:27957



5G NR n48 15MHz QPSK Middle Channel RB1-0 Port A+B, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB1-37 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz QPSK High Channel RB1-0 Port A, ID:27957



5G NR n48 15MHz QPSK High Channel RB1-37 Port A, ID:27957



5G NR n48 15MHz QPSK High Channel RB1-0 Port B, ID:27957



5G NR n48 15MHz QPSK High Channel RB1-37 Port B, ID:27957



5G NR n48 15MHz QPSK High Channel RB1-0 Port A+B, ID:27957



5G NR n48 15MHz QPSK High Channel RB1-37 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz QPSK Low Channel RB38-0 Port A, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB38-0 Port A, ID:27957



5G NR n48 15MHz QPSK Low Channel RB38-0 Port B, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB38-0 Port B, ID:27957



5G NR n48 15MHz QPSK Low Channel RB38-0 Port A+B, ID:27957



5G NR n48 15MHz QPSK Mid Channel RB38-0 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 15MHz QPSK High Channel RB38-0 Port A, ID:27957



5G NR n48 15MHz QPSK High Channel RB38-0 Port B, ID:27957



5G NR n48 15MHz QPSK High Channel RB38-0 Port A+B, ID:27957

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 20MHz QPSK Low Channel RB1-0 Port A, ID:27957



5G NR n48 20MHz QPSK Low Channel RB1-50 Port A, ID:27957



5G NR n48 20MHz QPSK Low Channel RB1-0 Port B, ID:27957



5G NR n48 20MHz QPSK Low Channel RB1-50 Port B, ID:27957



5G NR n48 20MHz QPSK Low Channel RB1-0 Port A+B, ID:27957



5G NR n48 20MHz QPSK Low Channel RB1-50 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 20MHz QPSK Middle Channel RB1-0 Port A, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB1-50 Port A, ID:27957



5G NR n48 20MHz QPSK Middle Channel RB1-0 Port B, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB1-50 Port B, ID:27957



5G NR n48 20MHz QPSK Middle Channel RB1-0 Port A+B, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB1-50 Port A+B, ID:27957

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 20MHz QPSK High Channel RB1-0 Port A, ID:27957



5G NR n48 20MHz QPSK High Channel RB1-50 Port A, ID:27957



5G NR n48 20MHz QPSK High Channel RB1-0 Port B, ID:27957



5G NR n48 20MHz QPSK High Channel RB1-50 Port B, ID:27957



5G NR n48 20MHz QPSK High Channel RB1-0 Port A+B, ID:27957



5G NR n48 20MHz QPSK High Channel RB1-50 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 20MHz QPSK Low Channel RB51-0 Port A, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB51-0 Port A, ID:27957



5G NR n48 20MHz QPSK Low Channel RB51-0 Port B, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB51-0 Port B, ID:27957



5G NR n48 20MHz QPSK Low Channel RB51-0 Port A+B, ID:27957



5G NR n48 20MHz QPSK Mid Channel RB51-0 Port A+B, ID:27957

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



Start Freq	Stop Freq	Integ BW	Lower dBm	Lower ΔLimit(dB)	Lower Freq (Hz)	Upper dBm	Upper ΔLimit(dB)	Upper Freq (Hz)
10.10 MHz	11.50 MHz	200.0 kHz	-33.38	(-20.38)	-10.11 M	-35.68	(-22.68)	10.11 M
11.50 MHz	30.00 MHz	1.000 MHz	-41.25	(-28.25)	-16.87 M	---	(---)	---
30.50 MHz	40.00 MHz	1.000 MHz	-52.98	(-27.98)	-30.74 M	---	(---)	---
11.50 MHz	20.00 MHz	1.000 MHz	---	(---)	---	-42.31	(-29.31)	11.50 M
20.50 MHz	30.00 MHz	1.000 MHz	---	(---)	---	-48.18	(-23.18)	22.70 M
30.50 MHz	40.00 MHz	1.000 MHz	---	(---)	---	-52.92	(-12.92)	33.61 M

5G NR n48 20MHz QPSK High Channel RB51-0 Port A, ID:27957



Start Freq	Stop Freq	Integ BW	Lower dBm	Lower ΔLimit(dB)	Lower Freq (Hz)	Upper dBm	Upper ΔLimit(dB)	Upper Freq (Hz)
10.10 MHz	11.50 MHz	200.0 kHz	-34.10	(-21.10)	-10.10 M	-34.81	(-21.81)	10.18 M
11.50 MHz	30.00 MHz	1.000 MHz	-36.58	(-23.58)	-11.59 M	---	(---)	---
30.50 MHz	40.00 MHz	1.000 MHz	-49.96	(-24.96)	-30.55 M	---	(---)	---
11.50 MHz	20.00 MHz	1.000 MHz	---	(---)	---	-34.73	(-21.73)	11.54 M
20.50 MHz	30.00 MHz	1.000 MHz	---	(---)	---	-40.28	(-15.28)	20.54 M
30.50 MHz	40.00 MHz	1.000 MHz	---	(---)	---	-48.25	(-8.25)	30.50 M

5G NR n48 20MHz QPSK High Channel RB51-0 Port B, ID:27957



Start Freq	Stop Freq	Integ BW	Lower dBm	Lower ΔLimit(dB)	Lower Freq (Hz)	Upper dBm	Upper ΔLimit(dB)	Upper Freq (Hz)
10.10 MHz	11.50 MHz	200.0 kHz	-30.39	(-17.39)	-10.11 M	-31.98	(-18.98)	10.14 M
11.50 MHz	30.00 MHz	1.000 MHz	-38.10	(-25.10)	-12.24 M	---	(---)	---
30.50 MHz	40.00 MHz	1.000 MHz	-49.78	(-24.78)	-31.88 M	---	(---)	---
11.50 MHz	20.00 MHz	1.000 MHz	---	(---)	---	-39.28	(-26.28)	11.54 M
20.50 MHz	30.00 MHz	1.000 MHz	---	(---)	---	-44.92	(-19.92)	21.14 M
30.50 MHz	40.00 MHz	1.000 MHz	---	(---)	---	-48.30	(-8.30)	33.33 M

5G NR n48 20MHz QPSK High Channel RB51-0 Port A+B, ID:27957

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n48 30MHz QPSK Low Channel RB1-0 Port A, ID:27957



5G NR n48 30MHz QPSK Low Channel RB1-77 Port A, ID:27957



5G NR n48 30MHz QPSK Low Channel RB1-0 Port B, ID:27957



5G NR n48 30MHz QPSK Low Channel RB1-77 Port B, ID:27957



5G NR n48 30MHz QPSK Low Channel RB1-0 Port A+B, ID:27957



5G NR n48 30MHz QPSK Low Channel RB1-77 Port A+B, ID:27957

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.