1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53

LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



LOW CHANNEL 6895

MID CHANNEL 6995

HIGH CHANNEL 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



LOW CHANNEL 6895



MID CHANNEL 6995



HIGH CHANNEL 7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – 106-Tones, RU Index-53

LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – 106-Tones, RU Index 54

LOW CHANNEL ANT 6 6895

LOW CHANNEL ANT 5 6895

MID CHANNEL ANT 6 6995

MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – SU MODE



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 53



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – 106-Tones, RU Index 54

LOW CHANNEL ANT 6 6895

LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995

HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX Antenna 6 + Antenna 5 SDM MODE (FCC + IC) – SU Mode



LOW CHANNEL ANT 6 6895



LOW CHANNEL ANT 5 6895



MID CHANNEL ANT 6 6995



MID CHANNEL ANT 5 6995



HIGH CHANNEL ANT 6 7095



HIGH CHANNEL ANT 5 7095

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.8.15. 802.11be EHT40 MODE IN THE UNII-8 BAND

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



STRADDLE CHANNEL, 6885

LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



STRADDLE CHANNEL, 6885

LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



STRADDLE CHANNEL, 6885

LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 6 MODE (FCC+IC) MOBILE – SU MODE



STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 53



STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 54



STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – 106-Tones, RU Index 56



STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

1TX Antenna 5 MODE (FCC+IC) MOBILE – SU MODE



STRADDLE CHANNEL, 6885



LOW CHANNEL 6965



HIGH CHANNEL 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – 106-Tones, RU Index 53



STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – 106-Tones, RU Index 54



STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965

LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – 106-Tones, RU Index 56

STRADDLE CHANNEL, Ant 6 6885

STRADDLE CHANNEL, Ant 5 6885

LOW CHANNEL ANT 6 6965

LOW CHANNEL ANT 5 6965

HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

2TX CDD MODE (FCC + IC) – SU MODE



STRADDLE CHANNEL, Ant 6 6885



STRADDLE CHANNEL, Ant 5 6885



LOW CHANNEL ANT 6 6965



LOW CHANNEL ANT 5 6965



HIGH CHANNEL ANT 6 7085



HIGH CHANNEL ANT 5 7085

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538, USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.