

5G NR n77 90MHz BPSK Low Channel RB1-0



5G NR n77 90MHz BPSK Middle Channel RB1-0



5G NR n77 90MHz BPSK Low Channel RB1-244



5G NR n77 90MHz BPSK Middle Channel RB1-244



5G NR n77 90MHz BPSK Low Channel RB243-0



5G NR n77 90MHz BPSK Middle Channel RB243-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 90MHz BPSK High Channel RB1-0



5G NR n77 100MHz BPSK Low Channel RB1-0



5G NR n77 90MHz BPSK High Channel RB1-244



5G NR n77 100MHz BPSK Low Channel RB1-272



5G NR n77 90MHz BPSK High Channel RB243-0



5G NR n77 100MHz BPSK Low Channel RB270-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 100MHz BPSK Middle Channel RB1-0



5G NR n77 100MHz BPSK High Channel RB1-0



5G NR n77 100MHz BPSK Middle Channel RB1-272



5G NR n77 100MHz BPSK High Channel RB1-272



5G NR n77 100MHz BPSK Middle Channel RB270-0



5G NR n77 100MHz BPSK High Channel RB270-0

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.4. 5G NR n77 (FCC Part 27 3700-3980MHz, MIMO)



5G NR n77 10MHz BPSK Low Channel RB1-0 Port A



5G NR n77 10MHz BPSK Low Channel RB1-23 Port A



5G NR n77 10MHz BPSK Low Channel RB1-0 Port B



5G NR n77 10MHz BPSK Low Channel RB1-23 Port B



5G NR n77 10MHz BPSK Low Channel RB1-0 Port A+B



5G NR n77 10MHz BPSK Low Channel RB1-23 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK Mid Channel RB1-0 Port A



5G NR n77 10MHz BPSK Mid Channel RB1-23 Port A



5G NR n77 10MHz BPSK Mid Channel RB1-0 Port B



5G NR n77 10MHz BPSK Mid Channel RB1-23 Port B



5G NR n77 10MHz BPSK Mid Channel RB1-0 Port A+B



5G NR n77 10MHz BPSK Mid Channel RB1-23 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK High Channel RB1-0 Port A



5G NR n77 10MHz BPSK High Channel RB1-23 Port A



5G NR n77 10MHz BPSK High Channel RB1-0 Port B



5G NR n77 10MHz BPSK High Channel RB1-23 Port B



5G NR n77 10MHz BPSK High Channel RB1-0 Port A+B



5G NR n77 10MHz BPSK High Channel RB1-23 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK Low Channel RB24-0 Port A



5G NR n77 10MHz BPSK Mid Channel RB24-0 Port A



5G NR n77 10MHz BPSK Low Channel RB24-0 Port B



5G NR n77 10MHz BPSK Mid Channel RB24-0 Port B



5G NR n77 10MHz BPSK Low Channel RB24-0 Port A+B



5G NR n77 10MHz BPSK Mid Channel RB24-0 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 10MHz BPSK High Channel RB24-0 Port A



5G NR n77 10MHz BPSK High Channel RB24-0 Port B



5G NR n77 10MHz BPSK High Channel RB24-0 Port A+B

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK Low Channel RB1-0 Port A



5G NR n77 15MHz BPSK Low Channel RB1-37 Port A



5G NR n77 15MHz BPSK Low Channel RB1-0 Port B



5G NR n77 15MHz BPSK Low Channel RB1-37 Port B



5G NR n77 15MHz BPSK Low Channel RB1-0 Port A+B



5G NR n77 15MHz BPSK Low Channel RB1-37 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK Mid Channel RB1-0 Port A



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A



5G NR n77 15MHz BPSK Mid Channel RB1-0 Port B



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port B



5G NR n77 15MHz BPSK Mid Channel RB1-0 Port A+B



5G NR n77 15MHz BPSK Mid Channel RB1-37 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.