

5G NR n77 15MHz BPSK High Channel RB36-0 Port A



5G NR n77 15MHz BPSK High Channel RB36-0 Port B



5G NR n77 15MHz BPSK High Channel RB36-0 Port A+B

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB1-0 Port A



5G NR n77 20MHz BPSK Low Channel RB1-50 Port A



5G NR n77 20MHz BPSK Low Channel RB1-0 Port B



5G NR n77 20MHz BPSK Low Channel RB1-50 Port B



5G NR n77 20MHz BPSK Low Channel RB1-0 Port A+B



5G NR n77 20MHz BPSK Low Channel RB1-50 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Mid Channel RB1-0 Port A



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port A



5G NR n77 20MHz BPSK Mid Channel RB1-0 Port B



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port B



5G NR n77 20MHz BPSK Mid Channel RB1-0 Port A+B



5G NR n77 20MHz BPSK Mid Channel RB1-50 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK High Channel RB1-0 Port A



5G NR n77 20MHz BPSK High Channel RB1-50 Port A



5G NR n77 20MHz BPSK High Channel RB1-0 Port B



5G NR n77 20MHz BPSK High Channel RB1-50 Port B



5G NR n77 20MHz BPSK High Channel RB1-0 Port A+B



5G NR n77 20MHz BPSK High Channel RB1-50 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB50-0 Port A



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port A



5G NR n77 20MHz BPSK Low Channel RB50-0 Port B



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port B



5G NR n77 20MHz BPSK Low Channel RB50-0 Port A+B



5G NR n77 20MHz BPSK Mid Channel RB50-0 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK High Channel RB50-0 Port A



5G NR n77 20MHz BPSK High Channel RB50-0 Port B



5G NR n77 20MHz BPSK High Channel RB50-0 Port A+B

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 25MHz BPSK Low Channel RB1-0 Port A



5G NR n77 25MHz BPSK Low Channel RB1-64 Port A



5G NR n77 25MHz BPSK Low Channel RB1-0 Port B



5G NR n77 25MHz BPSK Low Channel RB1-64 Port B



5G NR n77 25MHz BPSK Low Channel RB1-0 Port A+B



5G NR n77 25MHz BPSK Low Channel RB1-64 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 25MHz BPSK Mid Channel RB1-0 Port A



5G NR n77 25MHz BPSK Mid Channel RB1-64 Port A



5G NR n77 25MHz BPSK Mid Channel RB1-0 Port B



5G NR n77 25MHz BPSK Mid Channel RB1-64 Port B



5G NR n77 25MHz BPSK Mid Channel RB1-0 Port A+B



5G NR n77 25MHz BPSK Mid Channel RB1-64 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 25MHz BPSK High Channel RB1-0 Port A



5G NR n77 25MHz BPSK High Channel RB1-64 Port A



5G NR n77 25MHz BPSK High Channel RB1-0 Port B



5G NR n77 25MHz BPSK High Channel RB1-64 Port B



5G NR n77 25MHz BPSK High Channel RB1-0 Port A+B



5G NR n77 25MHz BPSK High Channel RB1-64 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.