14085 Howard Rd
Dayton, MD 21036

TRP Inc.

February 10, 2006

Federal Communications Commission
7475 Oakland Mills Rd
Columbia, MD 21045

Re: Medtronic Inc request for change in identification of a previously certified device

Gentlemen:

This Change of Identification request applies to a new FCC ID, as permitted under 47CFR 2.933(b) for a currently approved device. The currently authorized product has been certified by Cisco Systems Inc under FCC ID: LDK102040, granted October 27, 2000. This application will establish a new identification, FCCID: LF5-2091WB, for marketing purposes by Medtronic Inc.

No changes to the product will be made by Medtronic Inc and it will remain identical to the product certified by Cisco Systems under FCC ID: LKD102040. The original test results will remain applicable to and representative of the equipment bearing the changed identification.

Per 2.933(b)
1. The original identification is LDK102040
2. The original grant date is 10/27/2000
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.
.

Sincerely,

Phillip Inglis
Consultant to Medtronic.