Photo documentation of external of product

OK

OK

HUAWEI

CE0168

WARNING
1.Risk of explosion if batteryis replaced by an incorrect type;
2.Disconnection of antenna before battery is replaced;
3.Dispose of used batteries according to the instructions.

7 8 9 20 1 2 3 4 5 6 7