


PV Meter Ver 3.01
C12 left unpopulated
C8,C9 left unpopulated
C12 left unpopulated
Bead1 -populated by 0ohm resistor(0805)
C17 left unpopulated
Components inside the frame left unpopulated
R7,C22 left unpopulated


TMX325
TCPAVAY
K2
JP1
R1
R4
R3