












NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID6\_NS\_01\_26000\_40000\_#1




NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID16\_NS\_01\_0.009\_0.15\_#1



NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID16\_NS\_01\_0.15\_30\_#1





NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID16\_NS\_01\_30\_1000\_#1





NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID16\_NS\_01\_1000\_3000\_#1

NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+M\_TID16\_NS\_01\_3000\_6000\_#1
























NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID6\_NS\_01\_3000\_6000\_#1NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID6\_NS\_01\_6000\_26000\_#1NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID6\_NS\_01\_26000\_40000\_#1NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID16\_NS\_01\_0.009\_0.15\_#1NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID16\_NS\_01\_0.15\_30\_#1NTNV\_DC\_2A\_n78A-3700-3800\_PC3\_30\_5+100  
\_M+H\_TID16\_NS\_01\_30\_1000\_#1

