


EXHIBIT C – EUT INTERNAL PHOTOGRAPHS


Uncovered View



Mainboard Top View



Mainboard Bottom View



BLE function was disabled by software



Battery View

