


	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
	Test No: T5276	Test Report Photos	Page: 1 of 10



dB Technology
----- (Cambridge Ltd.) -----
EMC Testing EMC Consultancy EMC Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

PHOTOS FOR REPORT ON EMC TESTS

Performed at:
TWENTY PENCE TEST SITE

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Cyrus Audio Ltd

System 1 (6dac / 8dac + PSXR)

dated

20th March 2014

Document History


Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	27/03/14		Initial release		

Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*

	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 2 of 10


Photograph 1 8dac



8 dac

	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 3 of 10

Photograph 2 6dac



6 dac (same as 8 dac but no PSXR and different transformer)

	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 4 of 10

Photograph 3 PSXR




Photograph 4 Conducted Emissions - 8dac - USB Source



	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 5 of 10

Photograph 5 Conducted Emissions - 8dac - USB Source




	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
	Test No: T5276	Test Report Photos	Page: 6 of 10

Photograph 6 Conducted Emissions - 6dac - USB Source



	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
	Test No: T5276	Test Report Photos	Page: 7 of 10

Photograph 7 Conducted Emissions - 6dac - USB Source



	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 8 of 10

Photograph 8 Conducted Emissions - 6dac - USB Source




	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
Test No: T5276		Test Report Photos	Page: 9 of 10

Photograph 9 Radiated Emissions - 8dac - USB Source



Photograph 10 Radiated Emissions - 8dac - USB Source



	Report No: R3330 Issue No: 1	FCC ID: 2ABZXJG10	
	Test No: T5276	Test Report Photos	Page: 10 of 10

Photograph 11 Radiated Emissions - 6dac - USB Source

