

Audit Mode Request Letter

TIMCO Engineering, Inc.

Some errors found in the spot check report by JYT and request to update the original reports, this is to request audit mode of FCC ID: 2ACCJH107,

The updated reports which we will upload after audit mode.

The major change filed under this application and the relevant report numbers can be referred to the "Report Revision Explanation Letter form JYT_FCC ID 2ACCJH107".

Sincerely,



(signature)

(printed name) Jim Huang