



INTERTEK TESTING SERVICE
Equipment Photographs


(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs


(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs

(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs



(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs



(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs


(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040

INTERTEK TESTING SERVICE
Equipment Photographs

(Internal)



FCC ID: 2ACRI-PLI0040
IC: 12275A-PLI0040