



Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 1 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 2 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 3 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 4 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 5 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 6 of 10




Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 7 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 8 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 9 of 10





Internal Photos of EUT

Report No.: 60381602 001

Model No. : DS-K1T201AEF

Page: 10 of 10



--THE END--