



15MHz Middle QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:26:21

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:29:49

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:32:43

B7 , Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:23:27

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:24:20

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:25:14

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:26:42

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:27:35

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:28:28

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:29:52

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:30:45

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:31:38

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:33:00

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:33:54


20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:34:47

B12, Normal**1RB was the worst case****1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)**


ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:12:12

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)


ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:13:05

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)


ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:13:58

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)

ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:15:23


3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)

ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:16:16

3MHz_High_QPSK_1@0(30MHz~8.16GHz)


ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:17:08

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:18:29

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:19:22

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:20:15

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:21:39

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:22:39

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:23:31

B13, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:16:02

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:16:20

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:16:40

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:16:56

5MHz_High_QPSK_1@0(30MHz~8.87GHz)









ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:18:43

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 11.FEB.2025 20:19:01




B17 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:24:45

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:26:31

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:29:05

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:25:38

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:28:11

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 23.DEC.2024 16:29:58

B38 , Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 28.DEC.2024 18:48:51

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:52:12

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:53:06

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:54:26

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 17:55:21

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:56:14

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:57:45

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:58:40

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 17:59:33

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:00:56

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:01:51

20MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:02:44

B41 , Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 18:04:02

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:04:55

5MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 18:05:50

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:07:19

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Testers:Chin Qin
Date: 17.JAN.2025 18:08:15

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:09:10

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:10:37

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:11:31

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:12:25

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:13:49

20MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:14:42

20MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 17.JAN.2025 18:15:38

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:44:42

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:46:11

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:47:39

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:49:40

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:51:07

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:52:34

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:56:49

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:58:18

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 16:59:48

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 17:01:49

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 17:03:16


20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 16.JAN.2025 17:04:53


B42_1 , Normal
1RB was the worst case

1_5MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:13:45

1_5MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:14:41

1_5MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:15:36

1_10MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:16:35

1_10MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:17:31

1_10MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:18:28

1_15MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:19:27

1_15MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:20:31

1_15MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:21:27

1_20MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:22:25

1_20MHz_Middle_QPSK_1@0(30MHz~36.5GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:23:20

1_20MHz_High_QPSK_1@0(30MHz~36.5GHz)



ProjectNo.:2403A43118E-RF Tester:Chin Qin
Date: 28.DEC.2024 19:24:16

***** END *****