



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB36@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:10:54

n41_15MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:11:31

n41_15MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:11:40

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:12:13

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:12:21

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:12:54

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:13:02

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:13:37

n41_15MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:13:45

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:14:49

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:14:58

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:15:38


n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB50@0



n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB50@0




n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:17:56

n41_20MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:18:35

n41_20MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:18:44

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:19:18

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:19:27

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:20:01

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:20:10

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:20:46

n41_20MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:20:55

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:22:02

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:22:12

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:22:55

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:23:05

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:23:40

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:23:50

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:24:25

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:24:36

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:25:13

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:25:23

n41_30MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:26:03

n41_30MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:26:13

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:26:49

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:26:59

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:27:34

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:27:44

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:28:21

n41_30MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:28:32

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:29:40

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:29:53

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:30:37

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:30:49

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:31:27

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:31:39

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:32:17

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:32:29

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:33:09

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:33:21

n41_40MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:34:03

n41_40MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:34:16

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:34:53

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:35:06

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:35:44

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:35:56

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:36:35

n41_40MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:36:48

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:37:59

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:38:12

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:38:59


n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB128@0



n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB128@0




n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:41:56

n41_50MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:42:39

n41_50MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:42:53

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:43:33

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:43:46

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:44:26

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:44:39

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:45:21

n41_50MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:45:34

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:47:14

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:47:29

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:48:10

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:48:26

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:49:06

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:49:21

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:50:02

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:50:17

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:50:59

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:51:15

n41_60MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:52:00

n41_60MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:52:15

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:52:56

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:53:11

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:53:52

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:54:07

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:54:50

n41_60MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:55:05

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:56:21

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0



ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:56:39

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0



ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 10:57:30