



n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -33.21dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:32:32

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -32.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:33:37

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@244 -33.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:34:35

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0 -32.85dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:35:34

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@0 -33.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:36:38

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -33.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:37:37

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -32.99dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:38:36

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -33.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:39:45

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -32.99dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:40:44

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -33.69dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:41:43

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.54dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:42:47

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@272 -33.59dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:43:46


n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB270@0 -33.49dBm




n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@0 -33.54dBm



n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -33.38dBm




n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -33.66dBm




n78_1


n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -35.38dBm



n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -35.83dBm




n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -37.99dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:51:46

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -36.69dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:52:50

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -37.93dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:53:49

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -37.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:54:47

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -37.73dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:55:50

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -37.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 14:56:48


n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -37.97dBm




n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.98dBm




n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -35.84dBm




n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.88dBm




n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -34.83dBm



n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -37.44dBm




n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -37.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:03:50

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:05:00

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:05:58

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:06:56

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -34.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:08:03

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -35.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:09:01

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -37.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:10:00

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.78dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:11:04

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -37.78dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:12:02

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -37.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:13:00

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -37.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:14:45

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -37.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:15:44

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -37.26dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:16:43

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -35.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:04:32

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -36.83dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:05:36

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -37.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:27:21

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:06:46

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -37.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:32:53

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -37.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:33:52

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:34:56

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -37.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:35:55

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -37.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:36:54

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -37.93dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:40:01

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -35.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 15:38:02

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -36.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 15:39:01

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.64dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:10:02

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.11dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:07:54

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -37.94dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:08:58

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -37.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:13:22

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -37.72dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:11:12

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -37.68dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:12:17

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -37.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:12:29

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -34.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:10:25

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -37.84dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:11:27

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.91dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:15:41

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -35.62dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:13:37