



n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -37.72dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:14:39

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -37.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:18:57

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -38.24dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:16:52

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -37.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:17:55

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -37.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:22:13

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -36.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:20:08

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -37.97dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:21:11

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -37.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:25:35

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.73dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:23:25

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -37.37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:24:32

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -38.05dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:28:53

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -35.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:26:43

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:27:46

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -37.47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:32:12

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -35.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:30:06

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -37.50dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:31:09

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -38dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:35:26

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -35.80dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:33:20

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -38.12dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:34:23

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -37.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:38:41

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -37.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:36:35

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -37.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:37:37

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -35.31dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:39:51

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -37.50dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:40:54

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -37.91dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:41:57

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -36.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:43:04

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -37.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:44:08

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -37.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:45:10

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@0 -36.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:46:18

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -37.86dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:47:21

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -37.89dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:48:24

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -34.87dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:49:35

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -37.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:50:38

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -37.94dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:51:42

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -35.47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:52:50

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -38.12dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 16:53:53


n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -37.98dBm




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -37.85dBm




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -36.68dBm



n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -34.60dBm




n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -38.12dBm




n78_3


n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -35.47dBm




n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -36.50dBm




n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@23 -36.83dBm




n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -36.72dBm




n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.31dBm



n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@23 -36.12dBm




n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB24@0 -36.07dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:34:56

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@0 -36.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:36:18

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23 -36.30dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:37:36

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0 -36.92dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:38:54

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:41:45

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@37 -35.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JUN.2025 21:43:03

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.74dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:44:20

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.82dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:45:47

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@37 -36.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:47:04

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB36@0 -36.10dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:48:22

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.23dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:49:45

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.20dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 21:51:03

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.43dBm




ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 21:52:20

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -36.72dBm




ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 21:55:13

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@50 -36.53dBm




ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 21:56:30

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -36.40dBm




ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 21:57:49

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.90dBm



ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 21:59:17

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@50 -36.31dBm



ProjectNo.:2401A43118E-RF Testset:Rungfunmaster Liang
Date: 3..JUN.2025 22:00:35