



n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.05dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:32:21

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.31dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 12:16:24

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.48dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 12:17:17

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -42.19dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 12:48:45

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -47.20dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 12:46:55

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -47.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 12:47:50

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.02dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:00:38

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -47.25dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:01:34

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.61dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 04:59:31

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -43.77dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:01:13

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -46.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:02:33

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -47.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:04:22

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -46.99dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 13:03:34

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 13:04:29

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -46.92dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 05:09:16

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -47.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 13:05:33

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -45.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 13:06:27

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -46.74dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JPN.2025 05:14:11

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.68dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:07:32

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -44.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:08:27

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -47.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:19:06

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -46.69dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:09:33

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -43.37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:10:28

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.24dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:23:59

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -46.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:11:31

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -43.08dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:12:26

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -46.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:28:55

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:13:26

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -43.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 13:15:39

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 05:33:47

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -47.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 13:16:39

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -41.77dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 13:17:35


n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.49dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 05:38:40


n78_2

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@0 -47.80dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 17:03:41

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@23 -47.48dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 17:04:45

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB24@0 -43.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister LiJiang
Date: 3..JFN.2025 17:05:50

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.48dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:06:59

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@23 -47.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:08:04

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB24@0 -47.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:09:10

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@0 -47.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:10:20

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@23 -48.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:11:26

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB24@0 -47.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 17:12:31

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.66dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:15:29

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:16:35

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB36@0 -42.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:17:40

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:18:51

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@37 -47.47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:19:57

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 -47.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 18:21:02


n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.81dBm




n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@37 -46.49dBm




n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.06dBm




n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@0 -46.73dBm




n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@50 -47.19dBm



n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB50@0 -42.11dBm




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:30:46

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@50 -47.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:31:39

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 -47.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:32:32

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@0 -47.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:33:30

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@50 -47.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:34:23

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB50@0 -47.02dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:35:16

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@0 -47.21dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:19:40

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@77 -47.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:20:51

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB75@0 -47.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 4..JFN.2025 11:38:42

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:23:11

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@77 -47.33dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:24:19

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 -47.74dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 3..JFN.2025 19:25:26