




B38 , Normal**1RB was the worst case****5MHz_Low_QPSK_1@0(30MHz~27.2GHz)**


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:53:00

5MHz_Low_QPSK_25@0(30MHz~27.2GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:53:37

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:54:15

5MHz_Middle_QPSK_25@0(30MHz~27.2GHz)

ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:54:53


5MHz_High_QPSK_1@0(30MHz~27.2GHz)

ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:55:33

5MHz_High_QPSK_25@0(30MHz~27.2GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:56:11

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:57:18

10MHz_Low_QPSK_50@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:57:57

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:58:46

10MHz_Middle_QPSK_50@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:59:23

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:00:02

10MHz_High_QPSK_50@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:00:40

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:01:46

15MHz_Low_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:02:26

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:03:06

15MHz_Middle_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:03:46

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:04:26

15MHz_High_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:05:05

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:06:05

20MHz_Low_QPSK_100@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:06:44

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:07:23

20MHz_Middle_QPSK_100@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:08:04

20MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:08:51


20MHz_High_QPSK_100@0(30MHz~27.2GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:09:28

B41 , Normal**1RB was the worst case****5MHz_Low_QPSK_1@0(30MHz~27.9GHz)**


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:10:16

5MHz_Low_QPSK_25@0(30MHz~27.9GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:10:55

5MHz_Middle_QPSK_1@0(30MHz~27.9GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:11:35

5MHz_Middle_QPSK_25@0(30MHz~27.9GHz)

ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:12:14


5MHz_High_QPSK_1@0(30MHz~27.9GHz)

ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:12:54

5MHz_High_QPSK_25@0(30MHz~27.9GHz)


ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:13:33

10MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:14:35

10MHz_Low_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:15:16

10MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:15:55

10MHz_Middle_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:16:36

10MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:17:16

10MHz_High_QPSK_50@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:17:54

15MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:19:11

15MHz_Low_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:19:52

15MHz_Middle_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:20:32

15MHz_Middle_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:21:12

15MHz_High_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:21:53

15MHz_High_QPSK_75@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:22:33

20MHz_Low_QPSK_1@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:25:18

20MHz_Low_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:26:00

20MHz_Middle_QPSK_100@0(30MHz~27.9GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:27:00


20MHz_High_QPSK_1@0(30MHz~27.9GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:27:40


B66, Normal

20MHz_High_QPSK_100@0(30MHz~27.9GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 16:28:20

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:39:59


1.4MHz_Low_QPSK_6@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_6@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_6@0(30MHz~18.8GHz)



3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:44:39

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:45:11

3MHz_Middle_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:45:43

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:46:15

3MHz_High_QPSK_15@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:46:47

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:47:48

5MHz_Low_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:48:21

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:48:52

5MHz_Middle_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:49:24

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:49:56

5MHz_High_QPSK_25@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:50:28

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:51:36

10MHz_Low_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 01:52:07

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:00:46

10MHz_Middle_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:01:19

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:01:51

10MHz_High_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:02:29

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:04:08

15MHz_Low_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:04:41

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:05:13

15MHz_Middle_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:05:47

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:06:26

15MHz_High_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:06:59

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:08:32

20MHz_Low_QPSK_100@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:09:05

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:09:37

20MHz_Middle_QPSK_100@0(30MHz~18.8GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:10:10


20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:10:48


B7 , Normal

20MHz_High_QPSK_100@0(30MHz~18.8GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 7.DEC.2024 10:11:21

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:15:28

5MHz_Low_QPSK_25@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:16:06

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:16:44

5MHz_Middle_QPSK_25@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:17:21

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:17:58

5MHz_High_QPSK_25@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:18:42

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:19:40

10MHz_Low_QPSK_50@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:20:18

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:20:56

10MHz_Middle_QPSK_50@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:21:32

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:22:09

10MHz_High_QPSK_50@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:22:47

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:23:46

15MHz_Low_QPSK_75@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:24:25

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:25:04

15MHz_Middle_QPSK_75@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:25:41

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:26:19

15MHz_High_QPSK_75@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:26:56

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:27:54

20MHz_Low_QPSK_100@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:28:35

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:29:13

20MHz_Middle_QPSK_100@0(30MHz~26.7GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:29:50


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:30:28


B42_1 , Normal

20MHz_High_QPSK_100@0(30MHz~26.7GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:31:05

1_5MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:34:01

1_5MHz_Low_QPSK_25@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:34:40

1_5MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:35:20

1_5MHz_Middle_QPSK_25@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:35:58

1_5MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:36:39

1_5MHz_High_QPSK_25@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:37:18

1_10MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:38:03

1_10MHz_Low_QPSK_50@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:38:44

1_10MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:39:26

1_10MHz_Middle_QPSK_50@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:40:04

1_10MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:40:46

1_10MHz_High_QPSK_50@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:41:26

1_15MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:42:09

1_15MHz_Low_QPSK_75@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:42:48

1_15MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:43:26

1_15MHz_Middle_QPSK_75@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:44:06

1_15MHz_High_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:44:46

1_15MHz_High_QPSK_75@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:45:26

1_20MHz_Low_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:46:11

1_20MHz_Low_QPSK_100@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:46:50

1_20MHz_Middle_QPSK_1@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:47:32

1_20MHz_Middle_QPSK_100@0(30MHz~36.5GHz)




ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:48:13

1_20MHz_High_QPSK_1@0(30MHz~36.5GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:48:54

1_20MHz_High_QPSK_100@0(30MHz~36.5GHz)



ProjectNo.:2403Z104805E-RF Tester:Lingling Li
Date: 8.DEC.2024 15:49:33