



n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB1@0 -36.70dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:44:03

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB1@23 -37.05dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:44:52

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB24@0 -37.22dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:45:41

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -35.49dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:46:36

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@23 -36.92dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:47:25

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB24@0 -36.36dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmaster Liang
Date: 18.DEC.2024 09:48:15

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB1@0 -36.93dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:49:05

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB1@23 -37.19dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:49:58

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB24@0 -37.07dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:50:47

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:55:34

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.72dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:56:23

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.38dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:57:13

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.94dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:06:17

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@37 -37.06dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:07:07

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB36@0 -35.99dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:07:56

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.99dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:08:50

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.17dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:09:39

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.71dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:10:29

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB1@0 -36.61dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:27:51

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB1@50 -36.86dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:28:44

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM
QPSK_RB50@0 -36.94dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:29:36

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.18dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:30:33

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@50 -37.20dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:31:26

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB50@0 -36.79dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:32:19

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@0 -36.55dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:33:16

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@50 -36.29dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:34:08

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB50@0 -36.84dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:35:01

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.76dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:42:03

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@64 -35.32dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:42:55

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB64@0 -36.99dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 10:43:48

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.71dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:44:48

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@64 -36.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:45:41

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0 -36.53dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:46:35

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.42dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:47:33

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@64 -36.89dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:48:26

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB64@0 -36.39dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 10:49:19

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@0 -36.82dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:08:27

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@77 -35.66dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:09:20

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB75@0 -36.69dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:10:13

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.83dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:14:23

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@77 -36.22dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:15:16

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0 -36.55dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:16:08

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@0 -36.44dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:17:06

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@77 -37dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:17:59

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB75@0 -36.79dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:18:52

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB100@0 -36.31dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:26:52

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@0 -36.77dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:25:05

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@105 -36.48dBm




ProjectNo.: 2401Z104805E-RF Tester:Kungfumeister Liang
Date: 18.DEC.2024 11:25:59

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0 -36.86dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:29:37

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.63dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:27:51

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@105 -36.29dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:28:44

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB100@0 -36.73dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:32:22

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@0 -36.56dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:30:35


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@105 -36.51dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 11:31:28


n41

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@0 -36.39dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:34:15

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -37.07dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:35:09

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -36.33dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:36:02

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.47dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:37:01

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -36.16dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:37:53

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -36.25dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster, L.Jiang
Date: 18.DEC.2024 11:38:47

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@0 -36.86dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:39:45

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@23 -35.92dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:40:39

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB24@0 -37.07dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:41:33

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.61dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:44:39

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@37 -35.89dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:45:36

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.03dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 11:46:32