



n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@0 -33.95dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:22:14

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@50 -33.71dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:23:11

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB50@0 -32.85dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:24:07

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -33.55dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:25:12

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@77 -33.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:26:10

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -33.38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:27:06

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -32.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:28:08

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@77 -33.21dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:29:05

n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB75@0 -33.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:30:02

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@0 -33.85dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:31:04

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@77 -33.47dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:32:02

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB75@0 -33.78dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:32:59

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -33.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:35:59

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -33.92dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:34:04

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -33.76dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:35:02

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB100@0 -33.71dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:38:57

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.59dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:37:01

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@105 -33.71dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:37:58

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB100@0 -33.85dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:52:15

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@0 -33.22dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:42:13

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@105 -33.37dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:43:13

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -33.34dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:55:06

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -33.24dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:53:18

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -33.58dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:54:13

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB128@0 -33.40dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:57:52

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.43dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:56:05

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@132 -33.62dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 14:56:59

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0 -32.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 09:56:29

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@0 -32.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 09:53:44

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132 -33.31dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 09:55:07

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -33.57dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 10:00:48

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -33.60dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 09:58:03

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -33.64dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 09:59:27

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0 -33.27dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:55:00

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -32.33dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 10:59:13

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@161 -33.27dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:54:06

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0 -33.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:57:49

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@0 -33.37dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:55:59

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161 -32.17dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:56:54

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -33.51dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:00:39

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -33.56dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 12:58:51

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -33.23dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:59:45

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0 -33.18dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:03:27

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.07dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:01:38

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@188 -33.66dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:02:33

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0 -33.68dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:06:16

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@0 -33.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:04:27

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188 -32.71dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:05:21

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -33.41dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:07:18

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -33.38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:08:14

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -32.73dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 13:09:09

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.20dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:33:17

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@216 -32.30dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:34:15

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0 -32.61dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:35:13

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@0 -33.07dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:36:16

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216 -33.07dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:37:14

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0 -33.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:38:12

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -32.89dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:39:18

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -33.11dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:40:15

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -33.16dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:41:12

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -32.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:42:16

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@244 -32.34dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:43:14

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0 -33.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:44:13

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@0 -32.74dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:45:17

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244 -32.87dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:46:15

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0 -33.18dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:47:13