



n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -33.58dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:48:20

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -33.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:49:18

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -33.14dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:50:16

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:51:21

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@272 -32.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:52:21

n77_3_100MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB270@0 -33.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:53:20

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@0 -33.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:54:26

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272 -33.13dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:55:26


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0 -32.61dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:56:25


n78_1

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:18:43

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -36.39dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:19:45

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -37.60dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:20:46

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.84dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:21:54

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -36.96dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:22:55

n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -38.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:23:57

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:25:05

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -37.76dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:26:06

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -36.93dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:27:08

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:28:19

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -38.01dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:29:21

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:30:23

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.24dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:31:32

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -37.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:32:34

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -38.07dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 18:33:36

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.34dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 14:58:37

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.93dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 11:59:37

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.79dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 15:00:36

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -36.99dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 15:01:42

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -37.59dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 15:02:41

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -37.47dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 15:03:41

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 16:06:04

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -38.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 16:07:04

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -37.39dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 16:18:31

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -37.52dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:05:51

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -38.03dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:06:44

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -38.20dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:07:37

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -37.56dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:08:39

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -37.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:09:34

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -38.17dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:10:26

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.85dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:11:24

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -38.27dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:12:17

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -38.16dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:13:09

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.49dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:14:07

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -37.73dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:15:03

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -38.29dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:15:59

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -37.64dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:18:48

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -37.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:17:02

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -37.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfaster Liang
Date: 11.DEC.2024 09:17:55

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.21dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:21:34

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.95dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:19:46

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -38.17dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:20:41

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -38.26dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:24:20

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:22:33

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -37.96dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:23:26

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -36.80dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:27:30

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0 -37.88dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:25:23

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -37.63dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:26:26

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -38.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:30:17

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.43dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:28:28

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -37.77dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:29:23

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -37.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:33:12

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -38.09dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:31:23

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -37.54dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:32:17

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -37.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:36:10

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -37.73dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:34:14

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -37.50dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:35:15