



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:11:25

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:11:50

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:12:25

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:12:51

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:13:26

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:13:54

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:14:28

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:14:53

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:15:28

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:15:47

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:16:12

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:16:38

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:17:18

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:17:43

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:18:21

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:18:56

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:19:25

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:19:44

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:20:17

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:20:39

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:21:13

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:21:32

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:22:03

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:22:28

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:23:06

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:23:38

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:24:19

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:24:38

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:25:17

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:25:42

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:26:26

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:26:51

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:27:33

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:27:55

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:28:31

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:29:02

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:29:33

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:29:55

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:30:27

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:30:52

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:31:21

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:31:49

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:32:23

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:32:51

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:33:23

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:33:52

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:34:20

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:34:43

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:35:20

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:35:45

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:36:14

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:36:36

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:37:08

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:37:33

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:38:09

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:38:40

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:39:08

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:39:40

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:40:17

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:40:42

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:41:23

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:41:48

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:42:30

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:42:55

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:43:34

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:43:59

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:44:43

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:45:11

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:45:47

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:46:06

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:46:50

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 29.MAR.2022 09:47:19

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:47:57

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:48:25

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:14:14

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:49:32

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:50:04

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:50:32

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:51:06

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:51:28

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.MAR.2022 13:15:24

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:52:22

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:52:57

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:53:23


Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)



Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:54:58

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:55:20

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:55:52

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:56:24

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:57:03

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:57:25

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:57:59

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:58:21

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:58:58

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 29.MAR.2022 09:59:18

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 09:59:55

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:00:24

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:00:49

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:01:11

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:01:40

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:01:59

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:02:36

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:03:07

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:03:38

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:04:03

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:04:38

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:05:03

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:05:37

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:05:57

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:06:41

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:07:10

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:07:52

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:08:20

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:08:57

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:09:23

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 29.MAR.2022 10:09:58

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 29.MAR.2022 10:10:20

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 29.MAR.2022 10:11:02

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 29.MAR.2022 10:11:28