



Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:48:50

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:49:09

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:49:38

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:50:04

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:50:30

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:50:59

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:51:24

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:51:52

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:52:15

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:52:38

Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:53:07

Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:53:36

Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:54:03

Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:54:29

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 12.MAR.2022 13:54:58


Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 12.MAR.2022 13:55:24




Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:55:56

Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:56:22

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:56:56

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:57:22

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:57:56

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:58:24

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:58:52

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 13:59:11

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 13:59:41

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 14:00:04

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 14:00:33

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 14:00:56

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 14:01:25

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 14:01:50

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 12.MAR.2022 14:02:19


Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 12.MAR.2022 14:02:45




Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 14:03:18

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 14:03:44

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 14:04:17

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 12.MAR.2022 14:04:43

Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:05:45

Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:06:14

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:06:47

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:07:12

Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:07:35

Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:07:58

Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:08:29

Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:08:58

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:09:25

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:09:51

Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 12.MAR.2022 15:10:24


Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 12.MAR.2022 15:10:47




Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:11:18

Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:11:47

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:12:16

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:12:45

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:13:21

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:13:40

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:14:14

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:14:39

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 12.MAR.2022 15:15:15

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:15:41

Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 12.MAR.2022 15:16:10

Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 12.MAR.2022 15:16:36