




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB38@0 13.581MHz




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB38@0 13.575MHz




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB38@0 13.525MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.024MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 18.023MHz



n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB50@0 18.108MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB50@0 18.021MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB50@0 18.011MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB51@0 18.167MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB51@0 18.165MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB51@0 18.171MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB51@0 18.179MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.531MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 27.530MHz



n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB75@0 27.722MHz



n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB75@0 27.650MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB75@0 27.516MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB78@0 27.871MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB78@0 27.770MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB78@0 27.767MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB78@0 27.750MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.490MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 37.509MHz



n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB100@0 37.185MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB100@0 37.131MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB100@0 37.290MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB106@0 37.791MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB106@0 37.783MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB106@0 37.818MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB106@0 37.763MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 46.873MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 46.832MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB128@0 46.888MHz



n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB128@0 47.014MHz



n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB128@0 47.049MHz



n78_2_50MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB133@0 47.433MHz

