



n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -48.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:10:26

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:08:11

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -48.21dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:09:19

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -48dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:13:09

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -48.35dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:11:20

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -44.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:12:16

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.90dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:14:17

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -45.75dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:15:36

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.90dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:16:41

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:17:35

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -47.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:18:29

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -47.88dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:19:24

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -40.88dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:20:35

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.50dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:21:47

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.93dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:22:41

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -48.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:23:34

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -47.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:24:42

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -48.05dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:25:36

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:26:48

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -47.71dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:27:55

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -47.75dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:29:05

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -47.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:30:16

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -47.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:31:10

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -48.10dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:32:03

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -47.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:33:17

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.01dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:34:23

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -47.58dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:35:18

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.62dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:36:25

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.83dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:37:19

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.59dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:38:27

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -47.79dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:49:54


n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -47.93dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:40:13


n78_2

n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.64dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:41:26

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@0 -48.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 16:58:53

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@23 -48.20dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:00:02

n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB24@0 -46.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:00:56


n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -44.77dBm




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@23 -47.91dBm




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB24@0 -41.32dBm




n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@0 -42.33dBm




n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@23 -48.11dBm



n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB24@0 -47.22dBm




n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@0 -47.38dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:11:02

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@37 -48.12dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:09:42

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB36@0 -41.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:10:50

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.82dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:11:58

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@37 -47.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:13:07

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 -47.79dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:14:28

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@0 -47.46dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:15:22

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:16:16

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 -46.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:17:26

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@0 -47.90dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:18:20

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@50 -47.65dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:19:29

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB50@0 -48.24dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:20:23

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -48.02dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:21:17

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@50 -47.46dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:22:12

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 -48.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:23:21

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@0 -47.90dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:24:30

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@50 -47.45dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:25:42

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB50@0 -47.61dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:27:06

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@0 -45.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:28:16

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@77 -47.61dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:29:10

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB75@0 -47.74dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:30:19

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:31:38

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@77 -47.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:32:32

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 -47.88dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:33:27

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@0 -44.75dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:34:45

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@77 -47.90dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:36:01

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB75@0 -47.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:37:11

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -48.07dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:40:19

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@0 -48.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:38:05

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -48.14dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:39:14

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -45.84dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:43:30

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -44.98dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:41:28

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -47.86dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:42:22

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -47.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:46:27

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@0 -47.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:44:39

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -47.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:45:33

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -48.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:49:41

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@0 -45.98dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:47:35

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -47.74dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:48:31

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -45.79dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:53:13

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -45.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:50:55

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -47.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:52:04

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -48.12dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:56:29

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@0 -45.68dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:54:25

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -46.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:11:57

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -44.05dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:59:44

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@0 -46.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:57:41

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -46.23dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 17:58:50

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -47.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:14:16

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.73dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:13:07

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -47.45dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:02:07

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -47.53dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:06:49

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@0 -47.63dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:04:31

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -47.67dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:05:40

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -48.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:41:07

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@0 -47.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:39:07

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -47.65dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:40:00

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.96dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:44:05

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.02dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:15:24

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.81dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:43:13

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -47.47dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:46:55

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -48.17dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:44:58

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -48.01dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:45:51

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.85dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:47:48

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -47.73dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:48:41

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.94dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:49:48

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:50:41

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -47.63dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:51:48

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -48.04dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:52:55

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -46.01dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:16:19

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:54:41

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -48.05dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:55:48

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -48.14dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:56:41

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -47.47dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:57:34

n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -48.30dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:58:42

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 16:59:50

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -47.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:00:57

n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -48.10dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:02:16

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -48.15dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:03:24

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -46.23dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 18:17:14

n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -48.06dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:05:25

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -47.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:06:18

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -47.75dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:07:12

n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -47.58dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:08:05

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 11:43:35

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -45.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 7.AUG.2024 11:44:46

n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.28dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:10:59

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -48.01dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:12:07

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -47.85dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:13:15

n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.89dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 4.AUG.2024 17:14:23