



n66_30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0
-38.51dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:22:26

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@159
-38.17dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:23:14

n66_30MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB160@0
-38.24dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:24:03

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@0
-38.01dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:24:56

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB1@159
-38.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:25:45

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM QPSK_RB160@0
-37.80dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:26:34

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@0
-37.85dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:29:32

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@215
-38.42dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:30:20

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB216@0
-38.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:31:05

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0
-37.31dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:32:03

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@215
-37.97dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:32:52

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB216@0
-38.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 24.FEB.2025 13:33:43


n66_40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@0
-37.55dBm




n66_40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@215
-38.23dBm




n66_40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB216@0
-38.22dBm




n77_1
n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@0
-37.58dBm




n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB1@23
-38.08dBm



n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM QPSK_RB24@0
-37.49dBm




n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.86dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:25:11

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23
-37.67dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:26:17

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0
-37.97dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:27:21

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0
-37.14dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:28:32

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23
-37.77dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:29:41

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0
-38.04dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:30:50

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:32:08

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.87dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:33:17

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.88dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:34:26

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.69dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:35:41

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37 -37.74dBm
n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0 -37.57dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:36:50




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:38:00

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.28dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:39:14

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.98dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:40:19

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.94dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:41:29

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0
-38.20dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:42:45

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50 -37.66dBm
n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0 -37.73dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:43:51




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 16:44:57

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.69dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:46:12

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50
-38.11dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:47:18

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0
-37.58dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:48:24

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0
-37.84dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:49:56

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50
-38.20dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:51:02

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0
-37.85dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:52:08

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0
-37.95dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:53:22

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77
-38.20dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:54:28

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0
-37.72dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:55:34

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.52dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:56:45

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77
-36.90dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:57:51

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0
-37.69dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 16:58:57

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0
-37.84dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:00:08

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77
-38.18dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:01:14

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0
-37.47dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:02:21

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0
-37.81dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:03:43

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -37.30dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:04:49

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -37.23dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:05:56

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.92dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:07:11

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -37.99dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:08:18

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.69dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:09:25

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0
-37.63dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:10:57

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -37.60dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:12:03

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -38.06dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaater Liang
Date: 19.FEB.2025 17:13:09

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0
-37.96dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:14:24

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -37.98dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:15:30

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -37.47dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:16:38

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.91dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:17:49

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.18dBm



ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:18:56

n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.97dBm



ProjectNo.:2501P28739E-RF Tester:Kungfumaaster Liang
Date: 19.FEB.2025 17:20:02