




Band 2_1.4 MHz_Middle_QPSK_RB6#0




Band 2_3 MHz_Middle_QPSK_RB15#0



ProjectNo.:2401S34482E-RF Tester:Allen Bai


Date: 19.MAY.2024 16:31:48

Band 2_3 MHz_Middle_16QAM_RB15#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai

Date: 19.MAY.2024 16:32:01




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:35:02



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:35:15


Band 2_10 MHz_Middle_QPSK_RB50#0



ProjectNo.:2401S34482E-RF Tester:Allen Bai



Date: 19.MAY.2024 16:37:44

Band 2_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai

Date: 19.MAY.2024 16:37:58




Band 2_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:42:21


Band 2_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:42:35




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:43:49




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:44:03




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:46:49



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:47:02



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:49:10




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:49:27




Date: 19.MAY.2024 16:51:21




Date: 19.MAY.2024 16:51:34




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:53:31




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:53:48




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:55:48




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:56:01




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:57:22



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 16:57:38




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:00:05




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:00:21

Band 7_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:04:48

Band 7_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:05:01

Band 38_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:06:44

Band 38_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:07:07

Band 38_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:09:16

Band 38_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:09:32

Band 38_15 MHz_Middle_QPSK_RB75#0



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:11:50

Band 38_15 MHz_Middle_16QAM_RB75#0



ProjectNo.:2401S34482E-RF Tester:Allen Bai
Date: 19.MAY.2024 17:12:15

