


December 7, 2020

Dear Sir or Madam,

We, Frymaster LLC, request a change of FCC ID certification from WS2-WG7833B0 to 2AQ4D-5066500 due to a Class 2 permissive change. The original test report and data remain representative of this device and accurately represent the test results for this new FCC ID.

Yours sincerely,


Name: Ralph Macy
Title: Director of Engineering