

**MODEL:EB544N**

**FCC ID: 2ASD5-3355**

**INPUT: 120V~, 60Hz, 1600W**

**KEEP WARM: 1300W**

**CONVECTION: 1400W**

**MICROWAVE OVEN: 1000W, 2450MHz**



**This device complies with part 15 of the FCC Rules.**

**Operation is subject to the following two conditions:**

**(1) This device may not cause harmful interference.**

**(2) this device must accept any interference received.**

**including interference that may cause undesired operation.**

**This device complies with Part 18 of the FCC Rules.**

**THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE  
STANDARDS 21 CFR SUBCHAPTER J.**

**MANUFACTURED:MMYYYY**

**MADE IN CHINA**

**CAUTION**·THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

**WARNING**·TO PROVIDE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

·CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING.SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNABLE MOTOR, DAMPER MOTOR,L.V.TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).

·RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.

· NOT FOR BUILT-IN INSTALLATION.

· PLUG INTO A SEPARATE 15 AMP 120 VOLT AC OUTLET ONLY.

## Back/Rear Side of Device

