

Report No.: TB-FCC164847 Page: 7 of 18

Appendix IV **EUT Internal Photographs**

Photo 9 Internal of EUT




Photo 10 Appearance of PCB





Report No.: TB-FCC164847 Page: 8 of 18

Photo 11 Appearance of PCB




Photo 12 Appearance of PCB





Report No.: TB-FCC164847 Page: 9 of 18

Photo 13 Appearance of PCB




Photo 14 Appearance of PCB





Report No.: TB-FCC164847 Page: 10 of 18

Photo 15 Appearance of PCB





Photo 16 Appearance of PCB





Report No.: TB-FCC164847 Page: 11 of 18

Photo 17 Appearance of PCB





Photo 18 Appearance of PCB





Report No.: TB-FCC164847 Page: 12 of 18

Photo 19 Appearance of PCB




Photo 20 Appearance of PCB






Report No.: TB-FCC164847 Page: 13 of 18

Photo 21 Appearance of PCB



Photo 22 Appearance of PCB





Report No.: TB-FCC164847 Page: 14 of 18

Photo 23 Appearance of PCB





Photo 24 Appearance of PCB





Report No.: TB-FCC164847 Page: 15 of 18

Photo 25 Appearance of PCB






Photo 26 Appearance of PCB





Report No.: TB-FCC164847 Page: 16 of 18

Photo 27 Appearance of PCB



FCC ID: 2ASRQ-CP-2105

TB-RF-074-1.0