




Apricity

Internal Photos | FCC ID: 2AVFOARA-001V2 | IC: 25756-ARA001V2



Connect

(541) 204-4450
contact@apricitycode.com
www.apricitycode.com

Bend

2789 NW Lolo Drive
Bend, OR 97703


Boston

288 Norfolk Street
Suite 3A
Cambridge, MA 02139



Apricity

Internal Photos | FCC ID: 2AVFOARA-001V2 | IC: 25756-ARA001V2



Connect

(541) 204-4450
contact@apricitycode.com
www.apricitycode.com

Bend

2789 NW Lolo Drive
Bend, OR 97703


Boston

288 Norfolk Street
Suite 3A
Cambridge, MA 02139



Apricity

Internal Photos | FCC ID: 2AVFOARA-001V2 | IC: 25756-ARA001V2



LTE antenna patch attached to case

BT antenna patch attached to case

LTE Antenna: Linx, ANT-LPL-FPC-100,
5.6dBi, 6.5dBi, 4.9dBi, 5.2dBi, 5dBi, 5.3dBi,
2.9dBi (depends on band, see datasheet),
Flat Patch

BT Antenna: Pulse Larsen, W3334B0150, 5.5dBi, Flat Patch

Connect

(541) 204-4450
contact@apricitycode.com
www.apricitycode.com

Bend

2789 NW Lolo Drive
Bend, OR 97703


Boston

288 Norfolk Street
Suite 3A
Cambridge, MA 02139



Apricity

Internal Photos | FCC ID: 2AVFOARA-001V2 | IC: 25756-ARA001V2



WITHOUT SHIELD

Connect

(541) 204-4450
contact@apricitycode.com
www.apricitycode.com

Bend

2789 NW Lolo Drive
Bend, OR 97703


Boston

288 Norfolk Street
Suite 3A
Cambridge, MA 02139



Apricity

Internal Photos | FCC ID: 2AVFOARA-001V2 | IC: 25756-ARA001V2



WITH SHIELD (ACCESS LEVEL OF AN ELECTRICIAN/INSTALLER)

Connect

(541) 204-4450
contact@apricitycode.com
www.apricitycode.com

Bend

2789 NW Lolo Drive
Bend, OR 97703

Boston

288 Norfolk Street
Suite 3A
Cambridge, MA 02139