

01/11/2024

Subject: Class II permissive change Request

FCC ID: 2AZ9X-HBMFX

Granted on: 07/29/2021

To whom may concern:

Pursuant to CRF Section 2.1043, Thomann GmbH requests a Class II permissive change to update the filing. All of the changes are not effect to the RF performance, function and power.

Change list:

1. The small power supply board (auxiliary power supply) is changed to a linear transformer, and the main power transformer is unchanged;
2. The three glass tube fuses on the small power supply board are changed to box fuses;
3. Changes in the installation mode of the power amplifier IC (will affect the overall temperature rise).



Comparison between the old and new photos and circle the differences

Picture

Original:




new:



Original:

new:



Sincerely,

Signature:

Name: Gary zhang

Company Name: Ryder Industries Ltd