

Report No.:1812C50023312501

Page 1 of 52

# Appendix Test Data

Report No.:	1812C50023312501	Test Sample No.:	1-2-2
Start Test Date:	2025-1-16	Finish Test Date:	2025-5-19
Test Engineer:	Hussen Guan	Auditor:	Justin Feng
Temperature:	23.0℃	Relative Humidity:	46%
Pressure:	101kPa		


## Appendix A: 20dB Bandwidth

## **Test Result**

Test Mode	Antenna	Frequency [MHz]	20db EBW[MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
DH5	Ant1	2402	0.67	2401.69	2402.35		
DH5	Ant1	2441	0.66	2440.70	2441.37		
DH5	Ant1	2480	0.65	2479.71	2480.36		
2DH5	Ant1	2402	1.05	2401.47	2402.53		
2DH5	Ant1	2441	1.04	2440.48	2441.52		
2DH5	Ant1	2480	1.11	2479.44	2480.55		
3DH5	Ant1	2402	0.72	2401.65	2402.37		
3DH5	Ant1	2441	0.66	2440.70	2441.36		
3DH5	Ant1	2480	1.07	2479.46	2480.53		





## **Test Graphs**

































## Appendix B: 99% Occupied Bandwidth

## **Test Result**


Test Mode	Antenna	Frequency [MHz]	OCB [MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
DH5	Ant1	2402	0.60240	2401.7003	2402.3027		
DH5	Ant1	2441	0.80919	2440.5834	2441.3926		
DH5	Ant1	2480	0.73427	2479.6553	2480.3896		
2DH5	Ant1	2402	1.0699	2401.4575	2402.5275		
2DH5	Ant1	2441	1.0040	2440.4965	2441.5005		
2DH5	Ant1	2480	1.1089	2479.4515	2480.5604		
3DH5	Ant1	2402	0.68332	2401.6643	2402.3477		
3DH5	Ant1	2441	0.73127	2440.6464	2441.3776		
3DH5	Ant1	2480	1.0460	2479.4755	2480.5215		

## **Test Graphs**





























## **Appendix C: Maximum Conducted Output Power**

## **Test Result Peak**


Test Mode	Antenna	Frequency[MHz]	Conducted Peak Power[dBm]	Conducted Limit[dBm]	Verdict
DH5	Ant1	2402	2.35	≤20.97	PASS
DH5	Ant1	2441	2.26	≤20.97	PASS
DH5	Ant1	2480	2.14	≤20.97	PASS
2DH5	Ant1	2402	1.44	≤20.97	PASS
2DH5	Ant1	2441	0.97	≤20.97	PASS
2DH5	Ant1	2480	0.89	≤20.97	PASS
3DH5	Ant1	2402	1.14	≤20.97	PASS
3DH5	Ant1	2441	1.06	≤20.97	PASS
3DH5	Ant1	2480	0.94	≤20.97	PASS


## **Test Graphs**


































**Appendix D: Carrier frequency separation** 

## **Test Result**


Test Mode	Antenna	Frequency [MHz]	Result [MHz]	Limit[MHz]	Verdict
DH5	Ant1	Нор	1.313	≥0.670	PASS
2DH5	Ant1	Нор	0.994	≥0.740	PASS
3DH5	Ant1	Нор	1.029	≥0.713	PASS

## **Test Graphs**









Report No.:1812C50023312501

Page 19 of 52


## **Appendix E: Dwell Time**


## **Test Result**

Test	Antonna	Frequency	Burst Width	Total Hops	Result	Limit	Verdict
Mode	Antenna	[MHz]	[ms]	[Num]	[s]	[s]	verdict
DH5	Ant1	Нор	2.887	111	0.32	≤0.4	PASS
2DH5	Ant1	Нор	2.892	109	0.315	≤0.4	PASS
3DH5	Ant1	Нор	2.894	114	0.33	≤0.4	PASS




## **Test Graphs**
















Report No.:1812C50023312501


Page 23 of 52

## **Appendix F: Number of Hopping Channel**

## **Test Result**


Test Mode	Antenna	Frequency [MHz]	Result [Num]	Limit [Num]	Verdict
DH5	Ant1	Нор	79	≥15	PASS
2DH5	Ant1	Нор	79	≥15	PASS
3DH5	Ant1	Нор	79	≥15	PASS

## **Test Graphs**











Report No.:1812C50023312501

Page 25 of 52

# Appendix G: Conducted Band edge


## **Test Result**


Test	A 4	Ch.	Frequency	Ref. Level	Result	Limit	) /
Mode	Antenna	Name	[MHz]	[dBm]	[dBm]	[dBm]	Verdict
DH5	Ant1	Low	2402	2.27	-54.86	≤-17.73	PASS
DH5	Ant1	High	2480	1.96	-57.16	≤-18.04	PASS
DH5	Ant1	Low	Hop_2402	1.31	-49.25	≤-18.69	PASS
DH5	Ant1	High	Hop_2480	0.63	-51.71	≤-19.37	PASS
2DH5	Ant1	Low	2402	0.77	-57.59	≤-19.23	PASS
2DH5	Ant1	High	2480	0.49	-57.07	≤-19.51	PASS
2DH5	Ant1	Low	Hop_2402	-1.92	-51.13	≤-21.92	PASS
2DH5	Ant1	High	Hop_2480	0.91	-56.55	≤-19.09	PASS
3DH5	Ant1	Low	2402	0.82	-52.69	≤-19.18	PASS
3DH5	Ant1	High	2480	0.78	-57.27	≤-19.22	PASS
3DH5	Ant1	Low	Hop_2402	-0.39	-54.11	≤-20.39	PASS
3DH5	Ant1	High	Hop_2480	-2.42	-54.04	≤-22.42	PASS

Remark:1. Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose have been set in the 'offset' of the Spectrum Analyzer during the test.





## **Test Graphs**






































Report No.:1812C50023312501

Page 32 of 52

## **Appendix H: Conducted Spurious Emission**


## **Test Result**

Test			Freq. Range	Ref. Level	Result	Limit	.,
Mode	Antenna	Frequency[MHz]	[MHz]	[dBm]	[dBm]	[dBm]	Verdict
DH5	Ant1	2402	0~Reference	2.21	2.21		PASS
DH5	Ant1	2402	30~1000	2.21	-69.1	≤-17.79	PASS
DH5	Ant1	2402	1000~26500	2.21	-51.03	≤-17.79	PASS
DH5	Ant1	2441	0~Reference	2.08	2.08		PASS
DH5	Ant1	2441	30~1000	2.08	-68.72	≤-17.92	PASS
DH5	Ant1	2441	1000~26500	2.08	-52	≤-17.92	PASS
DH5	Ant1	2480	0~Reference	1.94	1.94		PASS
DH5	Ant1	2480	30~1000	1.94	-68.8	≤-18.06	PASS
DH5	Ant1	2480	1000~26500	1.94	-51.08	≤-18.06	PASS
2DH5	Ant1	2402	0~Reference	0.13	0.13		PASS
2DH5	Ant1	2402	30~1000	0.13	-68.95	≤-19.87	PASS
2DH5	Ant1	2402	1000~26500	0.13	-52.45	≤-19.87	PASS
2DH5	Ant1	2441	0~Reference	-0.33	-0.33		PASS
2DH5	Ant1	2441	30~1000	-0.33	-69.43	≤-20.33	PASS
2DH5	Ant1	2441	1000~26500	-0.33	-52.68	≤-20.33	PASS
2DH5	Ant1	2480	0~Reference	-0.48	-0.48		PASS
2DH5	Ant1	2480	30~1000	-0.48	-68.48	≤-20.48	PASS
2DH5	Ant1	2480	1000~26500	-0.48	-54.01	≤-20.48	PASS
3DH5	Ant1	2402	0~Reference	-0.10	-0.10		PASS
3DH5	Ant1	2402	30~1000	-0.10	-68.29	≤-20.1	PASS
3DH5	Ant1	2402	1000~26500	-0.10	-51.2	≤-20.1	PASS
3DH5	Ant1	2441	0~Reference	0.57	0.57		PASS
3DH5	Ant1	2441	30~1000	0.57	-69.04	≤-19.43	PASS
3DH5	Ant1	2441	1000~26500	0.57	-49.48	≤-19.43	PASS
3DH5	Ant1	2480	0~Reference	0.57	0.57		PASS
3DH5	Ant1	2480	30~1000	0.57	-68.49	≤-19.43	PASS
3DH5	Ant1	2480	1000~26500	0.57	-54.2	≤-19.43	PASS


Remark:Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose and attenuator factor s have been set in the 'TDF' of the Spectrum Analyzer during the test.




## **Test Graphs**



















































































Report No.:1812C50023312501

Page 47 of 52


# **Appendix I: Duty Cycle**


#### **Test Result**

Test Mode	Antenna	Frequency[MHz]	ON Time	Period	Duty Cycle	Duty Cycle
			[ms]	[ms]	[%]	Factor[dB]
DH5	Ant1	2402	2.88	3.76	76.60	1.16
DH5	Ant1	2441	2.88	3.76	76.60	1.16
DH5	Ant1	2480	2.88	3.76	76.60	1.16
2DH5	Ant1	2402	2.88	3.75	76.80	1.15
2DH5	Ant1	2441	2.88	3.75	76.80	1.15
2DH5	Ant1	2480	2.88	3.75	76.80	1.15
3DH5	Ant1	2402	2.88	3.75	76.80	1.15
3DH5	Ant1	2441	2.89	3.76	76.86	1.14
3DH5	Ant1	2480	2.88	3.75	76.80	1.15





# **Test Graphs**































---End---