

Xinchen Shenzhen Trading Co., Ltd.

Jun 30, 2024

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2BHHQ17Y

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

JiangFeng

A handwritten signature in black ink, appearing to read "Jiang Feng", written in a cursive style.