



Photographs of the Device

*Internal Front View – Transceiver Module Circuit Board Top View*




Photographs of the Device

*Internal Front View – Transceiver Module, Control Section*




Photographs of the Device

*Internal Front View – Transceiver Module, Exciter Section*




Photographs of the Device

*Internal Front View – Transceiver Module, Receiver Section*



Photographs of the Device

*Internal Front View – Power Amplifier Module, Cover Removed*




Photographs of the Device

*Internal Front View – Power Supply Module*



Photographs of the Device

*Internal Front View – Power Supply Module, Circuit Boards, Top View*




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC4819


Photographs of the Device

*Internal Front View – Backplane*



Photographs of the Device

*Internal Back View – Transceiver Module*



Photographs of the Device

*Internal Back View – Power Amplifier Module*



Photographs of the Device

*Internal Back View – Power Supply Module, Circuit Boards, Back View*



Photographs of the Device

*Internal Back View – Backplane*

