



December 16, 2010

FCC: ABZ89FT7638

Model 5490SM

Attestation Letter

To Whom It May Concern:

Canopy client device FCC ID: ABZ89FT7638 using client software 10.5 will not initiate any transmission on DFS frequencies. This includes transmissions for beacon ad-hoc peer-to-peer modes.

Sincerely,

A handwritten signature in black ink, appearing to read "SMP".

Steven M. Payne  
Canopy Regulatory Engineering  
Motorola