

September 23, 2002

Mr. Andy Leimer  
Authorization & Evaluation Division  
Federal Communications Commission Laboratory  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: Form 731 Confirmation Number: EA524079  
FCC ID: AZ499FT3081  
Correspondence Reference Number: 23985

Dear Mr. Leimer:

Motorola Inc., 1313 East Algonquin Road, Schaumburg, Illinois 60196, herein submits its response to your September 20, 2002 request for additional information on FCC ID: ABZ99FT3081, EA524079 via Correspondence Reference Number 23985.

Q1) Filing has Mot. P/Ns 68P81092C58-B Mobile Radios Installation Manual and 6866110R13-O CDM1550\_LS+ Two-Way Radio User Guide. User Guide states: "Before using this product, read the RF energy awareness information and operating instructions in the Product Safety and RF Exposure booklet enclosed with your radio (Motorola Publication part number 68P81095C99) to ensure compliance with RF energy exposure limits." Please submit "Product Safety and RF Exposure booklet"

R1) The Product Safety and RF Exposure Booklet 68P81095C99 is attached as a separate exhibit [RF Safety Booklet](#).

Q2) The Revised MPE table has the table split onto two pages. Please submit a new exhibit with this problem fixed. Please view the table before submission.

R2) The corrected file is attached as a separate exhibit [Corrected PMUD1765A Waris 220MHz 020712](#).

Sincerely,



James M. Zima

Principal Staff Engineer  
Motorola, Inc.  
Phone: (847) 576-3697

**MOTOROLA INC.**

**FCC ID: ABZ99FT3081**

FAX: (847) 538-4312  
Email: [jim.zima@motorola.com](mailto:jim.zima@motorola.com)

Attachments:

[RF Safety Booklet](#) (exhibit type: Users Manual)

[Corrected PMUD1765A Waris 220MHz 020712](#) (exhibit type: RF Exposure Info)