

December 15, 2010

To: Elite Electronic Engineering  
Re: Identification Change for *iDEN Multi-Carrier- Outdoor Pole Mount Transmitter*

Per CFR 47, Paragraph 2.933, Motorola respectfully requests a change in identification for the indicated transmitter.

The affected transmitter is as follows:

Existing FCC ID	Lower (MHz)	Upper (MHz)	New FCC ID
PURMCSERIESOPM	851.0125	868.9875	ABZMCSERIESSC

**(1) The original identification used**

The original identification used for the transmitter is *PURMCSERIESOPM*. This is a multi-carrier transmitter that is used in *iDEN* systems.

**(2) The date of the original grant**

The date of the original grant of equipment authorization is *08/27/2007*.

**(3) How the equipment bearing the modified identification differs from the original equipment**


The change requested is in identification only. There is no change in design, circuitry, or construction of the unit other than company logos and labeling. The front panels on the equipment have the Motorola logos rather than the RadioFrame Networks logos. The identification label also contains 'Motorola' as well as the updated FCC identification number, *ABZMCSERIESOPM*.

**(4) Whether the original test results continue to be representative / applicable**

All original test results currently on file with the commission are applicable and are representative of current and future shipping product. The equipment will be completely compatible and interchangeable with the existing equipment previously shipped by RadioFrame Networks. The form, fit, and function of the equipment is identical.

**(5) Exterior appearance photographs**

An image of the new label is shown below. The FCC ID label goes in the front inside door jam of the outdoor enclosure. External photographs of the unit are shown on the following page.



APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZMCSERIESOPM



*(Front View, Cabinet Partially Open)*



*(View Showing FCC Label Location)*

*iDEN Multi-Carrier Transmitter – ABZMCSERIESOPM*