



Intertek Testing Services

ETL SEMKO

Report No.: 9906543


Made! Charging

Tested By: Hong, Report No.: 9906543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100ms	AUTO	LN OFF	60dB

Final Measurement:	Transducer No.	Start	Stop	Name
X QF	3	9k	30M	EI078
Meas Time: 1 s				
Subranges: 16				
Res Margin: 20dB				



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906543

Mode: Charging

Tested By: Hong, Report No.: 9906543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
28.73500	25.1	48.0

* limit exceeded

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906543

Mode: Standby

Tested By: Hong, Report No.: 9906543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100ms	AUTO	LN OFF	60dB


Final Measurement: N VP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906543

Mode: Standby

Tested By: Hong, Report No.: 9906543

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100ms	AUTO	LN OFF	60dB

Final Measurement Results: -

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906543

Mode: Transmission

Tested By: Heng, Report No.: 9906543

Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450Hz	30M	5k	10k	PK	100us	AUTO LN OFF


Final Measurement: NQP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9906543

Mode: Transmission

Tested By: Hong, Report No.: 9906543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
16.03000	29.1	48.0

* limit exceeded

Ctrl. No.: N/A