

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

Below 1GHz (Horizontal: Y-axis/ Vertical: Y-axis)

Above 1GHz (Horizontal: X-axis/ Vertical: Z-axis)

X-axis



Y-axis



Z-axis



End of Report