

Mike Kuo

From: Takahashi Masanori [takahashi-masanori@jqa.jp]
Sent: June04日2004年Friday 8:15 PM
To: Mike Kuo
Cc: Mika Kaneko
Subject: Re: Sony Corporation , FCC ID: AK8MV65STF, Assessment NO.: AN04T3941



400-40065
y_MV-65ST__FM Tr



Test setup
photo.pdf

Dear Mr.Mike Kuo

I reply to your question.

> Question #1: Based upon section 13.1.1.1 Applied modulation of ANSI
> C63.4:2001, " If a device is equipped with input connectors for external
> modulation, typical modulating signals shall be applied.." In the test
> report, it is not clear how the audio modulation was applied during the
> tests. Please explain.

Sorry, I didn't perform to test of occupied band width at external input mode,
because I thought that DVD play back mode (color bar and 0dB sound level recorded disc) might be worst case.
Yesterday I retry the occupied band width measurement.
I was supplised that I used test disc was something wrong, and same result could not appear. The test disc was not recorded at 0dB sound level.
I made test disc again. And I heard to the manufacturer what specified maximum audio input level at external input.
The maximum input level at external input port was specified 0.775Vrms.
Therefore, I performed to test agin both DVD play mode and External input mode.
The attached test report is re-issued to include occupied band width re-test,
please refer to page 36 to 45.
If additionally information is need, please contact me.

Best regards,

JAPAN QUALITY ASSURANCE ORGANIZATION
EMC Engineering Dept. Testing Div.

Masanori Takahashi
Tel: +81-3-3416-0193 Fax: +81-3-3416-8290
E-mail: takahashi-masanori@jqa.jp

----- Original Message -----

From: "Mike Kuo" <MKUO@CCSEMC.com>
To: <takahashi-masanori@jqa.jp>
Cc: "Mika Kaneko" <MKaneko@CCSEMC.com>
Sent: Friday, June 04, 2004 3:26 AM
Subject: FW: Sony Corporation , FCC ID: AK8MV65STF, Assessment NO.: AN04T3941

>
>
> -----Original Message-----
> From: Compliance Certification Services [mailto:MKuo@ccsemc.com]
> Sent: Thursday, June 03, 2004 11:09 AM
> Subject: Sony Corporation , FCC ID: AK8MV65STF, Assessment NO.: AN04T3941
>
>

> Question #1: Based upon section 13.1.1.1 Applied modulation of ANSI
> C63.4:2001, " If a device is equipped with input connectors for external
> modulation, typical modulating signals shall be applied.." In the test
> report, it is not clear how the audio modulation was applied during the
> tests. Please explain.
>
> Best Regards
>
> Mike Kuo
>
> The items indicated above must be submitted before processing can continue
> on the above referenced application. Failure to provide the requested
> information within 60 days of the original e-mail date may result in
> application dismissal and forfeiture of the filing fee. Also, please note
> that partial responses increase processing time and should not be
> submitted.
> Any questions about the content of this correspondence should be directed
> to
> the e-mail address listed below the name of the sender.